



Detector was annealed after irradiation for 80 minutes at 60 C.
Measurements were taken at $T \sim -20\text{C}$